ROUTING SLIP FROM	HOPETH
TQ:	
City Hall Offices	ATTENTION OF:
Building Regulations	
City Clerk	
City Manager	
Finance	
Accounting	
Licensing	
Purchasing	
Geologist	
Health	
Air Pollution	
Clinic	
Law	
Mayor	
Mgnt. Info Study	Named and Address of the Address of
Personnel	
Planning	1361
Public Works Adm	
Engineering	
General Services	KARON
Sanitary Services	CHANDLOR
Traffic	TE CHEED THOU CHE C
Street Maint.	
OTHER OFFICES	
Airport Art Museum	7
Children's Home	NATURAL BARRA 191 1151
City Utilities	
Court	
Fire Dept.	
Library	
Manpower	
Parks	
Police Dept.	

City of Springfield, Missouri CITIZENS' INFORMATION SERV Date Receive: 4-8-60 Control Number: HE 111-4-80 Target Date for Correction/Investigation: Abatement Date: PART I Name of Location of Problem NATIONAL OIL CO. Caller FRANK VICK Address 2405W KERANNEY Name and Phone No. 865 9766 Phone No. PLEASECALC PART II Request for Service _____ Complaint Nature of Inquiry: Recommendation Other PART III *Topic: "THEY WASH TRUCKS & THE OIL GOESDOWN THE STREET TO MR VICKS HOUSE." Send Copy of Reply To Referred 1) All 2) Received By: AS HONFOLTON Department: Howelf To: PART IV Replys SOME OF THE WASTE OIL IS GOING UNDER THE STREET AND INTO AFIELD.

*Attach additional sheets as needed Form001-CM (5-74)

Department: Hopen

Drafted By: ASH

2405 W. Kenangy

Acknowledgment Sent:

By: Phone Letter Other

Date Citizen Advised:



BOB C. FYJ , please file R.

June 5, 2001

Mr. and Ms. Robert Keith Greene 2405 W. Kearney Springfield, Missouri 65803-2032

Dear Mr. and Ms. Greene,

I was asked to respond to a storm water concern that you had about brush being placed in a drainage ditch. The area in question is north of Kearney Street and east of West Avenue.

Our records indicate that the property that the drainage ditch is on is privately owned and not a publicly maintained ditch. This means that the property owners should maintain the ditch.

My suggestion would be to identify the persons placing the brush in the ditch and ask them to remove the brush. If you can't identify the persons responsible then you or the property owners should remove the brush to ensure that storm water can flow uninhibited through the drainage ditch.

If I can be of any further help or if you want to discuss this matter further then call me at 864-1965.

Sincerely,

Stephen A. Meyer

Superintendent of Street Maintenance

cc Randy Lyman

